



TANGERINE WOODS IRRIGATION MAINTENANCE

Proposal Cost / Service – Summary
February 3, 2024

Tangerine Woods Monthly Irrigation Inspection Price includes all labor, material and equipment.

- A. Inspection: All irrigation zones shall be inspected one (1) time per month.
- B. 12 visits per year to ensure proper operations.
- C. Any issues that require adjustments or cleaning filters, heads, rotors, spray nozzles will be performed during the monthly inspection.
- D. All repairs to the system shall be done on a time and materials basis.
- E. All zones will be turned on for a minimum of five minutes to check for any coverage issues or any broken irrigation components.

Total of services: 12

ANNUAL: \$3,780.00
MONTHLY: \$315.00

Contractor Signature

Client Signature

Contractor Printed

Client Printed

Title

Title

Sprinkler | Nozzle Repair

Install Replace Drip line (per ft. cast)	\$1.70
Install Replace Maxi-Jet Nozzle	\$3.00
Raise Straighten head in turf	\$4.00
Install Replace Rotor Nozzle	\$4.00
Install Replace Maxi-Jet Stake Assembly	\$6.50
Install Replace Spray Nozzle	\$5.00
Cap off head (any type)	\$8.00
Install Replace MP-Rotor Nozzle	\$13.00
Replace 6" Spray head	\$24.00
Raise blocked head with riser	\$24.00
Relocate head (any type)	\$29.00
Replace 2" Spray head	\$30.00
Replace Rotrr head	\$38.00
Add 6" Spray head with pipe	\$55.00
Add 2" Spray head with pipe	\$68.00
Add Rotor head with pipe	\$95.00

Valves

Replace 1" Valve (Standard)	\$140.00
Replace 1 1/2" Valve (Standard)	\$250.00
Replace 2" Valve (Standard)	\$340.00
Replace 1" Valve (Scrubber)	\$235.00
Replace 1 1/2" Valve (Scrubber)	\$365.00
Replace 2" Valve (Scrubber)	\$445.00
Install RB 1" Drip Control Valve	\$400.00
Install RB 1 1/2" Drip Control Valve	\$635.00

Pipe Repair

Repair Drip Line break	\$5.00
Repair Flex pipe leak	\$11.00
Repair 1/2" zone leak	\$45.00
Repair 3/4" zone line leak	\$45.00
Repair 1" zone line leak	\$67.00
Repair 1 1/4" zone line leak	\$70.00
Repair 1 1/2" zone line leak	\$90.00
Repair 2" zone line leak	\$95.00
Repair Main line leak (all sizes)	based on time and materials

Valve Solenoids

Replace Rainbird 24V Solenoid	\$75.00
Replace Hunter 24V Solenoid	\$40.00
Replace Irritrol 24V Solenoid	\$45.00
Replace Rainbird EZ Bleed Solenoid	\$75.00
Replace Rainbird DC Latch Solenoid	\$65.00
Replace Hunter DC Latch Solenoid	\$60.00
Replace Irritrol DC Latch Solenoid	\$58.00

Valve Boxes

Replace Valve Box 7" Round	\$28.00
Replace Valve Box 7" Round (purple)	\$30.00
Replace Valve Box 10" Round	\$52.00
Replace Valve Box 10" Round (purple)	\$62.00
Replace Valve Box Rectangular	\$85.00
Replace Valve Box Jumbo	\$125.00
Troubleshoot Valve Not Operating	based on time and materials

Controllers	
RB ESP Modular Controller 4 Station	\$225.00
RB ESP SMT Controller 4 Station	\$505.00
RB ESP SM-3 3 Station Module	\$60.00
RB ESP SM-6 6 Station Module	\$120.00
RB ESP LXME 8 Station Module	\$628.00
RB ESP LXM SM-8 8 Station Module	\$185.00
RB ESP LXM SM-12 12 Station Module	\$275.00
Hunter ACC 1200 Controller	\$2,700.00
Hunter ACC 2 Metal Cabinet	\$2,600.00
Hunter Decoder Module	\$1,115.00
Hunter ACC 6 Station Module	\$350.00
Hunter Node 100 1 Station Battery Clock	\$175.00
Hunter Node 200 2 Station Battery Clock	\$285.00
Hunter Node 400 4 Station Battery Clock	\$340.00
Hunter XC Hybrid 6 Station Control	\$240.00
Hunter XC Hybrid 10 Station Control	n/a
Hunter XC Hybrid 12 Station Control	\$300.00
Install Replace 9V Battery Back-Up	\$6.00
Weathermatic 1600 Web-based Control	\$1,368.00
Weathermatic 1600 with Flow Capability	\$1,711.00
Weathermatic 1624 24 Zone Web based	\$1,560.00
Weathermatic 1624 with Flow Capability	\$1,902.00
Weathermatic 4800 Web-based Control	\$1,751.00
Weathermatic 4800 with Flow Capability	\$2,093.00
Weathermatic 4 Station Exp. Module	\$75.00
Weathermatic 12 Station Exp. Module	\$213.00

Sensor	
Install Hunter Mini Clock (wired)	\$77.00
Install Hunter Wireless Rain Sensor	\$135.00
Install Hunter Solar Sync Sensor	\$215.00
Install Rainbird Wireless Rain Sensor	\$140.00
Install Hunter Wireless Solar Sync	\$262.00
Install Weathermatic Flow Sensor 1"	\$933.00
Install Weathermatic Flow Sensor 1 1/2"	\$1,009.00
Install Weathermatic Flow Sensor 2"	\$1,084.00

Decoders Wire Surge Protection	
Replace ICD-100 Single Station Decoder	\$190.00
Replace ICD-200 Two Station Decoder	\$285.00
Install Ground Rod with 6" Copper Wire	\$252.00
Install Intermatic Secondary Surge Arrester	\$174.00
Install 4' x 96" Copper Grounding Plate	\$980.00

Pump Well	
Basic Inspection of Irrigation Pump	\$240.00
Conduct Water Quality Test (per sample)	\$80.00

